SAFETY DATA SHEETS

This SDS packet was issued with item:

077078967

N/A

Rev: A

1. CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

Product Name: Product Group:

QUICK PEG REFRACTORY GERAMIC FIBER PRODUCT Vident Product Name: Quick Peg

N 1/18/05 J ame: Quick Peo

Chemical Name: Synonymial:

VITREOUS ALUMINOSILICATE FIBER

Vident Part Number: A47-320

RCF, ceramic fiber, synthetic vitreous fiber (SVF), man-made vitreous fiber (MMVF), man-made mineral fiber (MMMF)

Manufacturer/Supplier: FUNCTIONAL DESIGNS, INC.

1018 W. 41ST

AUSTIN, TEXAS 78756

800-627-4461

Distributed By:

Vident

3150 E. Birch St. Brea. Ca 92821

Phone: (714) 961-6200 Fax: (714) 961-6299

CHEMTREC Applat:

CHEMTREC will provide assistance for chemical emergencies. Call 1-800-424-9300

2. COMPOSITION / INFORMATION ON INGREDIENTS

COMPONENTS	<u>CAS NUMBER</u>	<u> % BY WEIGHT</u>
Water	7732-18-5	65-70
Refractories, Fibers, Aluminosilicate	142844-00-6	20-25
Silica (amorphous)	7631- 86 -8	5-10
Hydroxyethylcellulose	9004-62-0	1-3

(See Section 8 "Exposure Controls / Personal Protection" for exposure guidelines)

3. HAZARDS IDENTIFICATION

EMERGENCY OVERVIEW

GAUTIONI MAY BE HARMFUL IF SWALLOWED.
MAY CAUSE SKIN AND EYE IRRITATION.

DRIED, ABRADED PRODUCT MAY CAUSE RESPIRATORY TRACT IRRITATION AND POSE POSSIBLE CANCER HAZARD BY INHALATION.

(See Section 11 for more information)

CHRONIC EFFECT

There has been no increased incidence of respiratory disease in studies examining occupationally exposed workers, in animal studies, long-term laboratory exposure to doses hundreds of times higher than normal occupational exposures has produced fibrosis, lung cancer, and mesothelioma in rats or hamsters. The fibers used in those studies were specially sized to maximize rodent respirability.

1/18/05

303*0724 Rev: A

OTHER POTENTIAL EFFECTS

TARGET ORGANS:

Respiratory Tract (nose & throat), Eyes, Skin

If dried, airborne product is inhaled in sufficient quantity, may cause temporary, mild mechanical initation to respiratory tract. Symptoms may include scratchiness of the nose or throat, cough or chest discomfort.

EYE IRRITATION:

May cause temporary, mild mechanical irritation. Fibers may be abrasive; prolonged contact may cause damage to the outer surface of the eye,

SKIN IRRITATION:

Exposure to dried product may cause temporary, mild mechanical initiation. Exposure may also result in inflammation, rash or fiching.

GASTROINTESTINAL IRRITATION:

Unlikely route of exposure. Small amounts swallowed incidental to normal handling operations are not likely to cause injury.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE:

Pre-existing medical conditions, including dermatitis, asthma or chronic lung disease may be aggravated by exposure; individuals who have a history of allergies may experience greater amounts of akin and respiratory initiation.

HAZARD CLASSIFICATION

Although studies, involving occupationally exposed workers, have not identified any increased incidence of respiratory disease, results from animal testing have been used as the basis for hazard classification. In each of the following cases, the conclusions are qualitative only and do not rest upon any quantitative analysis suggesting that the hazard actually may occur at current occupational exposure levels.

In October 2001, the International Agency for Research on Cancer (IARC) confirmed that Group 2b (possible human carcinogen) remains the appropriate IARC classification for RCF.

The Seventh Annual Report on Carcinogens (1994), prepared by the National Toxicology Program (NTP), classified respirable RCF and glasswool as substances reasonably anticipated to be carcinogens.

The American Conference of Governmental Industrial Hygienists (ACGIH) has classified RCF as "A2-Suspected Human Carcinogen."

The Commission of The European Communities (DG XI) has classified RCF as a substance that should be regarded as if it is carcinogenic to man.

The State of California, pursuant to Proposition 65. The Sale Drinking Water and Toxic Enforcement Act of 1986, has listed "ceramic fibers (airborne fibers of respirable size)" as a chemical known to the State of California to cause cancer.

The Canadian Environmental Protection Agency (CEPA) has classified RCF as "probably carcinogenic" (Group 2).

The Canadian Workplace Hazardous Materials Information System (WHMIS) – RCF is classified as Class D2A – Materials Causing Other Toxic Effects

The Hezardous Materials Identification System (HMIS) -

Health 1" Flammability 0 Reactivity 0 Personal Protection Index: X (Employer Determined) ("denotes potential for chronic effects)

Rev: A 1/18/05

4. FIRST AID MEASURES

FIRST AID PROCEDURES

RESPIRATORY TWACT (nose & throat) IRRITATION:

If respiratory tract irritation develops, move the person to a dust free location. Get medical attention if the irritation continues. See Section 8 for additional measures to reduce or stiminate exposure.

EYE IRRITATION:

If eyes become initiated, flush immediately with large amounts of lukewarm water for at least 15 minutes. Eyelids should be held away from the eyeball to ensure thorough rinsing. Do not rub eyes. Get medical attention if imitation penalists.

SKIN IRRITATION:

if skin becomes irritated, remove solled clothing. On not rub or scratch exposed skin, Wash area of contact thoroughly with scap and water. Using a skin cream or lotion after washing may be helpful.

GASTROINTESTIMAL IRRITATION:

If gastrointestinal tract initiation develops, move the person to a dust free environment.

NOTES TO PHYSICIANS:

Skin and respiratory effects are the result of temporary, mild mechanical initation; fiber exposure does not result in allergic manifestations.

5. FIRE FIGHTING MEASURES

NFPA Codes:

Flansmability: 0

Haalth: 1

Reactivity: Ú

Special: 0

NFPA Unusual Hazards: None Flammable Properties: None

Flash Point: None

Hazardous Decomposition Products: Thermal decomposition of binder from first or from first heat of product may release smoke, carbon monoxide, carbon dioxide, aldehydes, and carboxylic acids. Use adequate ventilation or other precautions to eliminate exposure to vapors resulting from thermal decomposition of binder. Exposure to thermal decomposition furnes may cause respiratory tract irritation, bronchial hyper-reactivity or an asthmatic-type response.

Unusual Fire and Explosion Hazard: None

Extinguishing Modia: Use extinguishing media autable for type of surrounding fire.

6. ACCIDENTAL RELEASE MEASURES

SPILL PROCEDURES

Avoid creating eliborne dust. Dust suppressing cleaning methods such as wet sweeping or vacuuming should be used to clean the work area, if vacuuming, the vacuum must be equipped with a HEPA filter. Compressed sir or dry sweeping should not be used for cleaning.

MSDS-0724 Rev: A 1/18/05

7. HANDLING AND STORAGE

Normal conditions of use and application are not expected to release respirable particulates of airborne fibers. Removal of used product, sanding, scraping, or otherwise destroying the integrity of the dried product may result in the release of particulates and fibers. During such operations where fibers could possibly be released. appropriate respiratory protection should be provided as discussed below and/or in Section 8 under Respiratory Protection.

STORAGE

Store in original container in a dry erea, Keep container closed when not in use.

HANDLING

Handle ceramic fiber carefully. Limit use of power tools unless in conjunction with local exhaust. Use hand tools whenever possible. Frequently clean the work area with HEFA filtered vecuum or wet sweeping to minimize the accumulation of debris. Do not use compressed air for clean-up.

EMPTY CONTAINERS

Product packaging may contain residue. Do not reuse.

8. EXPOSURE CONTROLS/PERSONAL PROTECTION

EXPOSURE QUIDELINES - RCF

Section 4. Annual Control of the Con		MANUFACTURER REG
Refractories, Fibers,	None Established*	0.5 f/cc, 8-hr, TWA**
Aluminosilicate		

- * There is no specific regulatory standard for RCF in the U.S. OSHA's "Particulate Not Otherwise Regulated (PNOR)* standard (29 CFR 1910.1000, Subpart Z, Air Conterminants) applies generally; Total Dust 15 mg/m3; Respirable Fraction 5 mg/m³.
- *** The Refractory Ceramic Fibers Coalition (RCFC) has sponsored comprehensive textcology and epidemiology studies to identify potential RCF-related health offects [see Section 11 for more details], consulted experts familier with fiber and particle science, conducted a thorough review of the RCF-related scientific literature, and further evaluated the data in a state-of-the-art quantitative risk assessment. Based on these efforts and in the absence of an OSHA PEL, RCFC has adopted a recommended exposure guideline, as measured under NIOSH Method 7400 B. The manufacturers' REG is intended to promote occupational health and safety through prudent exposure control and reduction and it reflects relative technical and economic feasibility as determined by extensive industrial hygiene monitoring efforts undertaken pursuant to an agreement with the U.S. Environmental Protection Agency.

OTHER OCCUPATIONAL EXPOSURE LEVELS (OEL)

RCF-related occupational exposure limits vary internationally. Regulatory OEL examples include: Australia - 0.5 Vcc; Austria - 0.5 Vcc; Canada - 0.5 to 1.0 Vcc; Denmark - 1.0 Vcc; France - 0.8 Vcc; Germany - 0.5 Vcc; Netherlands - 1.0 f/cc; New Zeatand - 1.0 f/cc; Norway - 2.0 f/cc; Potand - 2.0 f/cc; Sweden - 1.0 f/cc; United Kingdom - 2.0 f/cc. Non-regulatory OEL examples include: ACGIH TLV 0.2 f/cc; RCFC REG 0.5 f/cc. The objectives and criteria underlying each of these OEL decisions also vary. The evaluation of occupational exposure limits and determining their relative applicability to the workplace is best performed, on a case-by-case basis, by a qualified industrial Hydienist.

EXPOSURE GUIDELINES - OTHER INGREDIENTS

Rev: A 1/18/05

COMPONENTS	OSHA PEL	MANUFACTURER REG
Water	None established	None established
Silica (antorphous)	Share and district and the second sec	None established
l-tydroxyethylcellulose	SiO2	None established
All Markey (1992)	None established	

OTHER OCCUPATIONAL EXPOSURE LEVELS (OEL)

Non-regulatory OEL examples include: ACGIH TLVs (TWAs): Water - None established. Silica (amorphous) - 10 mg/m². Hydroxyethylcollulose - None astablished.

ENGINEERING CONTROLS

Use engineering controls such as local exhaust ventilation, point of generation dust collection, down draft work stations, emission controlling tool dealgns, and materials handling equipment designed to minimize airborne fiber emissions.

PERSONAL PROTECTION EQUIPMENT

Respiratory Protection - RCF:

When engineering and/or administrative controls are insufficient to maintain workplace concentrations within the 0.5 f/cc REG, the use of appropriate respiratory protection, pursuant to the requirements of OSHA Standards 29 CFR 1910.134 and 29 CFR 1926,103, is recommended. The following information is provided as an example of appropriate respiratory protection for aluminosificate fibers. The evaluation of workplace hazards and the identification of appropriate respiratory protection is best performed, on a case by case basis, by a qualified Industrial Hygienist.

MANUFACTURER'S RESPIRATORY PROTECTION RECOMMENDATIONS WHEN HANDLING RCF PRODUCTS		
Respirable Airborne Fiber Concentration (levels are 8-hr. time-weighted averages)	Respirator Recommendation †	
Not yet determined but expected to be below 5.0 I/cc based on operation	Half-face, air purifying respirator equipped with a NIOSH certified P100 particulate filter cartridge	
"Reliably" less than 0.5 t/cc	Optional .	
0.5 f/cc to 5.0 f/cc	Half-face, air purifying respirator equipped with a NIOSH certified P100 particulate filter cartridge	
5.0 f/cc to 25 f/cc	Full-facepiece, air purifying respirator equipped with a NIOSH certified P100 particulate filter cartridge or PAPR	
Greater than 25 f/cc	PAPR with tight-fitting full facepiece or a supplied air respirator in continuous flow mode	
When individual workers request respiratory protection as a matter of personal comfort or choice where exposures are "reliably" below 0.5 f/cc	A NIOSH certified respirator, such as a disposable perticulate respirator, or respirators with filter cartridges rated N95 or better	

The P100 recommendation is a conservative default choice; in some case, solld arguments can be made that other respirator types (e.g.; N95, R99, etc.) may be suitable for some tasks or work environments. The P100 recommendation is not designed to limit informed choices, provided that reaptratory protection decisions comply with 29 CFR 1910,134.

5124547975 DR:RICHARD KING

MSDS-0724

Rev: A 1/18/05

Wear safety glasses with side shields or other forms of eye protection in compliance with appropriate OSHA standards to prevent eye irritation. The use of contact lenses is not recommended, unless used in conjunction with appropriate eye protection. Do not touch eyes with solled body parts or materials. If possible, have eye-washing facilities readily available where eye irritation can occur.

9. PHYSICAL AND CHEMICAL PROPERTIES

ODOR AND APPEARANCE:

White, odorless, fibrous material

CHEMICAL FAMILY: BOILING POINT: Vitreous Aluminosilicate Fibers Not Applicable

WATER SOLUBILITY (%):
MELTING POINT:

Not Soluble in Water 1760° C (3200° F)

SPECIFIC GRAVITY: VAPOR PRESSURE: 2.50 - 2.75 Not Applicable Not Applicable

VAPOR DENSITY (Air = 1):

Not Applicable

% VOLATILE: MOLECULAR FORMULA:

Not Applicable Not Applicable

10. STABILITY AND REACTIVITY

CHEMICAL STABILITY:

Stable under conditions of normal use.

INCOMPATIBILITY:

Soluble in hydrofluoric acid, phosphoric sold, and concentrated

alkali.

CONDITIONS TO AVOID:

None.

HAZARDOUS DECOMPOSITION PRODUCTS:

Thermal decomposition of binder from first or from first heat of product may release smoke, carbon monoxide, carbon dioxide, aldehydes, and carboxylic acide. Use adequate verifiation or other precautions to eliminate exposure to vapors resulting from thermal decomposition of binder. Exposure to thermal decomposition fumes may cause respiratory tract irritation, bronchial hyper-reactivity or an

asthmatic-type response.

HAZARDOUS POLYMERIZATION:

Not Applicable.

11. TOXICOLOGICAL INFORMATION

Normal conditions of use and application are not expected to release respirable particulates of airborne fibers. Removal of used product, sanding, scraping, or otherwise destroying the integrity of the dried product may result in the release of particulates and fibers. The toxicological information below applies to the aluminositicate fiber portion of the dried product.

HEALTH DATA SUMMARY

Epidemiological studies of RCF production workers have indicated no increased incidence of respiratory disease nor other significant health effects. In animal studies, long-term, high-dose inhalation exposure resulted in the development of respiratory disease in rate and hamsters.

EPIDEMIOLOGY

The University of Cincinnati is conducting an engoing epidemiologic investigation. The evidence obtained from employees in U. S. RCF manufacturing facilities is as follows:

- 1) There is no evidence of any fibratic lung disease (interstitial fibrasis) from evaluations of chest X-rays.
- There is no evidence of an elevated incidence of lung disease among RCF manufacturing employees.

MSDS-0724 Rev: A 1/18/05

- 3) In early studies, an apparent statistical "trend" was observed, in the exposed population, between RCF exposure duration and some measures of lung function. The observations were dinically insignificant. If these observations were made on an individual employee, the results would be interpreted as being within the normal (predicted) respiratory range. A more recent longitudinal study of employees with 5 or more pulmonary function tests found that there was no effect on lung function associated with RCF production experience. Initial data (circa 1987) seemed to indicate an interactive effect between smoking and RCF exposure; more recent data, however, found no interactive effect. Nevertheless, to promote good health, RCF employees are still actively encouraged not to smoke.
- 4) Pleural plaques (thickening along the chest wall) have been observed in a small number of RCF employees. Some studies appear to show a relationship between the occurence of pleural plaques on chest radiographs and the following variables: (a) years since RCF production hire date; (b) duration of RCF production employment; and (c) cumulative RCF exposure. The best evidence to date indicates that pleural plaques are a marker of exposure only. Pleural plaques are not associated with pulmonary impairment. The pathogenesis of pleural plaques remains incompletely understood; however, the mechanism appears to be an inflammatory response caused by inhaled fibers.

TOXICOLOGY

A number of toxicological studies designed to identify any potential health effects from RCF exposure have been completed. In one study, conducted by the Research and Consulting Company, (Geneva, Switzerland), rate and hamsters were exposed to 30 mg/m² (about 200 fibers/cc) of specially-prepared RCF for 6 hours/day, 5 days/week, for up to 24 months. In rate, a statistically significant increase in lung tumors was observed; two mesothellomas (cancer of the pleural lining between the chest wall and lung) were also identified. Hamsters did not develop lung tumors; however, interstitial fibrosis and mesothelloma was found. Some, in the scientific community, have concluded that the "maximum tolerated dose" was exceeded and that significant particle contamination was a confounding issue; therefore, these study findings may not represent an accurate assessment of the potential for RCF to produce adverse health effects.

In a related multi-dose study with a similar protocol, other rats were exposed to doses of 16 mg/m³, 9 mg/m³, 3 mg/m³ which corresponds to about 115, 75, and 25 fibers per cubic centimeter respectively. This study found no statistically significant increase in lung cancer. Some cases of pleural and parenchymal fibrosis were seen in the 16 mg/m³ dose group. Some cases of mild fibrosis and one mesothetioma were observed in the 9 mg/m³ group. No acute respiratory effects were seen in the rats in the 3 mg/m³ exposure group, which suggests that there may be a dose/response threshold, below which irreversible respiratory impacts do not occur.

Other toxicological studies have been conducted which utilized non-physiological exposure methods such as intrapleural, intraperitoneal and intratracheal implantation or injection. Some of these studies have found that RCF is a potential cardinogen. Some expects, however, suggest that these tests have limited relevance because they bypass many of the biological mechanisms that prevent fiber deposition or facilitate fiber clearance.

12. ECOLOGICAL INFORMATION

No ecological concerns have been identified.

13. DISPOSAL CONSIDERATIONS

WASTE MANAGEMENT

To prevent waste materials from becoming airborne during waste storage, transportation and disposal, a covered container or plastic bagging is recommended.

DISPOSAL

RCF, as manufactured, is not classified as a hazardous waste according to Federal regulations (40 CFR 261). Any processing, use, alteration or chemical additions to the product, as purchased, may eiter the disposal requirements. Under Federal regulations, it is the waste generator's responsibility to properly characterize a waste material, to determine if it is a "hazardous" waste. Check local, regional, state or provincial regulations to identify all applicable disposal requirements.

MSDS-0724 Rev: A 1/18/05

14. TRANSPORT INFORMATION

U.S. DEPARTMENT OF TRANSPORTATION (DOT)

Hazard Class:

Not Regulated

United Nations (UN) Number: North America (NA) Number:

Not Applicable Not Applicable

Labels: Placarda: Not Applicable Not Applicable

Bill of Lading:

Product Name

INTERNATIONAL

Canadian TDG Hazard Class & PIN: Not regulated

Not classified as dangerous goods under ADR (road), RID (train) or IMDG (ship).

15. REGULATORY INFORMATION

UNITED STATES REGULATIONS

EPA.

Superfund Amendments and Reauthorization Act (SARA) Title III - This product does not contain any substances reportable under Sections 302, 304, 313, (40 CFR 372). Sections

311 and 312 (40 CFR 370) apply (delayed hazard).

Toxic Substances Control Act (TSCA) - All substances in this product are listed, as required, on the TSCA inventory. RCF has been assigned a CAS number; however, it is a

simple mixture and therefore not required to be listed on the TSCA inventory. The

components of RCF are listed on the inventory.

Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) and the Clean Air Act (CAA) - RCF contains fibers with an average diameter greater than

one micron and thus is not considered a hazardous air pollutant.

OSHA:

Comply with Hazard Communication Standards 29 CFR 1910.1200 and 29 CFR 1926.59

and the Respiratory Protection Standards 29 CFR 1918.134 and 29 CFR 1926.103.

California:

Ceramic fibers (airborne particles of respirable size)" is listed in Proposition 65, The Safe

Drinking Water and Toxic Enforcement Act of 1986 as a chemical known to the State of

California to cause cancer.

Other States: RCF products are not known to be requiated by states other than California; however, state and local OSHA and EPA regulations may apply to these products. If in doubt, contact your

local regulatory agency.

INTERNATIONAL REGULATIONS

Canada:

Canadian Workpiace Hazardous Materials Information System (WHMIS) - RCF is

classified as Class D2A - Materials Causing Other Toxic Effects

Canadian Environmental Protection Act (CEPA) - All substances in this product are listed.

as required, on the Domestic Substance List (DSL)

European Union: European Directive 97/69/EC classified RCF as a Category 2 cardnogen; that is it "should

be regarded as if it is carcinogenic to man."

Rev: A 1/18/05

16. OTHER INFORMATION

RCF DEVITRIFICATION

As produced, all RCF fibers are vitreous (glassy) materials which do not contain crystalline silica. Continued exposure to elevated temperatures may cause these fibers to devitrify (become crystalline). The first crystalline formation (multite) begins to occur at approximately 985° C (1865° F). Crystalline silica (cristobalite) formation may begin at temperatures of approximately 1200° C (2192° F). The occurrence and extent of crystalline phase formation is dependent on the duration and temperature of exposure, fiber chemistry and/or the presence of fluxing agents. The presence of crystalline phases can be confirmed only through laboratory analysis of the "hot face" liber.

IARC's evaluation of crystalline silica states "Crystalline silica inhaled in the form of quartz or cristobalite from occupational sources is carcinogenic to humans (Group 1)" and additionally notes "carcinogenicity in humans was not detected in all industrial circumstances studied" (IARC Monograph Vol. 68, 1997). NTP lists all polymorphs of crystalline silica amongst substances which may "reasonably be anticipated to be carcinogens".

IARC and NTP did not evaluate after-service RCF, which may contain various crystalline phases. However, an analysis of after-service RCF samples obtained pursuant to an exposure monitoring agreement with the USEPA, found that in the furnace conditions sampled, most did not contain detectable levels of crystalline silfca. Other relevant RCF studies found that (1) simulated after-service RCF showed little, or no, activity where exposure was by inhalation or by intraperitoneal injection; and (2) after-service RCF was not cytotoxic to macrophage-like cells at concentrations up to 320 g/cm² - by comparison, pure quartz or cristobalite were significantly active at much lewer levels (circa 20 g/cm²).